

.....RPM.....		.....SET.....		.....10E.....		.....RPM.....	
SR	SS	SS	PS	PULL	SR	10E	MV/II
					L0	425	
					L1	555	
100	700	SLOW			L2	745	700
107	750	A					
121	850	B	1	1		875	
136	950	C			L3	960	
150	1050	D	2				
164	1150	E					
	1200		3		L4	1225	1200
186	1300	F					
207	1450	G	4				
229	1600	H			L5	1600	
250	1750	I		2		1750	
	1810		5				1800
					H0	1850	
271	1900	J					
293	2050	K					
314	2200	L	6				
343	2400	M					
					H1	2500	2400
371	2600	N					
	2650		7				
400	2800	O					
429	3000	P					3000
	3220		8				
464	3250	Q					
					H2	3300	
500	3500	R		3		3500	
							3600
543	3800	S					
	3850		9				
586	4100	T					
					H3	4200	4200
629	4400	U					
							4600
671	4700	V					
729	5100	W					
743	5200	FAST					5200
					H4	5500	
					H5	6800	