


Drive System Feb 1981



• Note the 'A' straight headstock is incorrect for this Period "B" was in Use

*Idler Shaft and Eccentric were updated in later machines