

BILL OF MATERIALS

# PCS	DESCRIPTION	PART NAME	SIZE	# PCS
2	A Bench End	Face	3/4 x 6-1/2 x 7-1/2	2
		Side	3/4 x 3-1/2 x 7-1/2	4
1	B Headrest		3/4 x 3-1/2 x 4-1/2	4
1	C Tie Bar		3/4 x 2-1/2 x 3-3/4	2
1	D Pivot Arm Base	Bottom	3/4 x 2-3/4 x 3	2
		Side	3/4 x 2-1/8 x 2-3/4	2
1	E Pivot Arm	Front	3/4 x 1-1/2 x 4	2
		Back	3/4 x 2-5/8 x 3	1
2	F Hinge Pin		3/8 DIA. x 1-1/4	2
2	G Upper Ways		1" DIA. x 17-1/2	2
2	H Lower Ways		1" DIA. x 17-3/4	2
1	J Headstock		3/4 x 4-1/2 x 6	7
1	K Spindle Crank	Crank	1" DIA. x 7-1/2	1
		Arm	5/8 DIA. x 2	1
		Handle	3/8 DIA. x 2	1
1	L Carriage		3/4 x 2 x 5-1/2	2
2	M Vertical Table Support		5/8 DIA. x 6	1
2	N Protractor Tilt Stop		1/8 x 2-1/4 x 1-3/4	2
1	P Table		3/4 x 4-1/2 x 6-1/2	1
2	Q Pivot Pin		3/8 DIA. x 1-1/2	1
8	R Stop Pin	Saw Pin	3/8 DIA. x 3/4	1
		Table Support Pin	3/8 DIA. x 1"	2
		Headstock, Protractor & Carriage Pins	3/8 DIA. x 1-1/2	3
		Tie Bar Pin	3/8 DIA. x 2	1
		Pivot Arm Pin	1/2 DIA. x 1-1/2	1
1	S Saw Blade		3/16 x 3-1/2 x 3-1/2	2
1	T Drill Chuck		1" DIA. x 4-1/2	1
1	U Miter Gauge	Face	1/8 x 5/8 x 1-3/4	1
		Base	1/4 x 3/4 x 1-3/4	1
		Bar	1/4 x 3/8 x 4	1
1	V Extension Table	Legs	5/8 DIA. x 3-3/4	2
		Top	3/4 x 1 x 6-1/2	1