






Mark 7 - Mark V 520



Mark V 505 - 510



Mark V Model 500

Table Service Parts Exploded Diagrams

Please note the Table Support Tubes on the 500 are not as widely spaced as the 505 - 510 -520 - Mark 7 Table Support Tubes and therefore the Carriages supporting them are different and the reason the wider Saw Guards from later units will not fit the earlier 500's. One would have to upgrade all three: The table, the carriage, and the Saw Guard etc.

Side-By-Side Shopsmith Mark 7 - Mark V 520 with Mark V 505 -510 and Original Mark V 500 Table Exploded Parts Diagram

Prepared by Everett L. Davis 8 Jul 2015